

Release Notes

E-Mix, Compulink and Videolink;

Version: UNA04R02.imf

Last version: UNA04R01.imf

General Information

1. CMX

CMX is not supported in Emix-2 with 4 outputs.

2. Redundancy

The redundancy feature is not supported in this software.

3. Updating software

It is recommended that when updating software to the E-mixes or Compulinks/Videolinks, to shut down any VC's being generated on the net at that time. Either turn off or go to to Service Tools on any consoles generating VC's, or change the Id to one with no VC transmission. This allows better utilization of the network. It is also recommended if updating a lot of nodes to use a slower speed, as set in "updating software" menu in Netserver software. Setting the speed to less than ¼ of the fastest speed is adequate.

If an Emix or node has a problem when updating software it will be necessary to turn the node off then on in order to attempt to burn software again.

4. Vc table sending requirements

It is required to send all VC tables to the Emix 2's in "multiple blocks" as set in the Netserver software under "Communication" menu and "options". It is now the default option. Note that consoles are sending VC tables in multiple blocks.

Bug Fixes

1. When there were network inconsistencies the Emix LCD display would jump to the default display making it impossible to request a table or make any modifications to the Emix. This no longer happens.

Known Bugs.

1. At the moment only 3 CompuLINKs work with Sabre.
2. When VC traffic is heavy the E-Mix push buttons many respond slowly.
3. The hold DMX function needs to be enabled, disabled and then enabled again in order to be functional.