

Release Notes

Photon

version: PHA05R07.imf
PHA05R07.tim
PGA05R07.imf
PGA05R07.tim

Service DMPA26B5

Tools:

Last PHA05R06.imf
version:

SB – 500	Version	Type
PAL rev. A/B U67	SB50U67A.Q SB52U67A.Q	revised memory map
PAL rev C U67	SB51U67A.Q SB53U67A.Q	revised memory map
Keyboard CAN S/W	PHOTOA08 PHOTOA09 (supports internal SMPTE)	

Bug Fixes

1. A/B Crossfader

- 1.1 When GO was pressed, faders moved out of limit, and automatic fade completed, the GO key was disabled when faders were taken to limit. This is now fixed. Thank you to BEO, Holland.

2. Submaster

- 2.1 Channels submastered on a controller who's slider level was between 1 and 99% would be bumped to full when it's flash key was pressed. This does not happen anymore. Thank you to Ernst from Austria.