

Release Notes

Animator Plus/Compact Plus

10.6.98

version: ML3C03R7.imf

ML3C03R5.tim

CM3C03R5.tim

Service Tools: DMLA25R4

Last version: ML3C03R6.imf

ML3C03R5.tim

CM3C03R5.tim

EPROM

Keyboard MKB96D21

Output MOUTR03

Bugs Fixed

1. Big Spots

- 1.1 Loading the Mix device only when there were Big Spots in the configuration corrupted the Big Spots, braking the link between PALa and PALb. This is now fixed. Thank you Stephen Plotkin.
- 1.2 After examining a memory or examining Delta, Big Spots patched to spot number 49 or over were corrupted. This does not happen anymore. Thank you Stephen Plotkin.

Known Bugs

1. Loading a show with Warning Difference corrupts the parameter to wheel assignments when the difference is the number of spots and/or DMX input. When the difference is the number of channels or dimmers this does not happen. Work around: avoid loading through Warning Difference by first loading the configuration of the show.
2. It is impossible to store a snap when a loop is running on A/B. Work around: store the snap when the loop is finished or before running the loop.
3. There are problems using block simulation.