

## Release Notes

### Animator Plus/Compact Plus

**version: ML3C03R8.imf**

**ML3C03R5.tim**

**CM3C03R5.tim**

**Service Tools: DMLA25R4**

Last version: ML3C03R7.imf

ML3C03R5.tim

CM3C03R5.tim

EPROM

Keyboard                    MKB96D21

Output                      MOUTR03

### Bugs Fixed

#### 1. SMPTE

- 1.1 Sometimes, a short time after an Event was triggered it was erroneously triggered a second time at random. This does not happen anymore. Thank you Patrick at Crystal, France.

### Known Bugs

1. Loading a show with Warning Difference corrupts the parameter to wheel assignments when the difference is the number of spots and/or DMX input. When the difference is the number of channels or dimmers this does not happen. Work around: avoid loading through Warning Difference by first loading the configuration of the show.
2. It is impossible to store a snap when a loop is running on A/B. Work around: store the snap when the loop is finished or before running the loop.
3. There are problems using block simulation.