

Release Notes

Photon

26.10.99

version: PHA05R06.imf
PHA05R06.tim
PGA05R06.imf
PHA05R06.tim
Service Tools: DMPA26B4

Last version: PHA05R05.imf

SB – 500	Version	Type
PAL rev. A/B U67	SB50U67A.Q SB52U67A.Q	revised memory map
PAL rev C U67	SB51U67A.Q SB53U67A.Q	revised memory map
Keyboard CAN S/W	PHOTOA08 PHOTOA09 (supports internal SMPTE)	

Bugs Fixed

1. Memory modification

- 1.1 Sometimes modifying a memory using STORE STORE changed the memory time to Profile. This does not happen anymore.
- 1.2 When the selected memory was a blackout the sequence **[MEMORY #] [wheel]** jammed the console. This is now fixed.

2. SMPTE

- 2.1 Sometimes Events that had already operated at their designated SMPTE time were randomly triggered again. This does not happen anymore. Thank you Patrick at Crystal, France.