

Release Notes

Spark

19.11.00

version: SPA05R08.imf

SPA05R07.tim

Service Tools: DMPA26B5

Last version: SPA05R07.imf
SPA05R04.tim

SB – 500	Version	Type
PAL rev. A/B U67	SB50U67A.Q SB52U67A.Q	revised memory map
PAL rev C U67	SB51U67A.Q SB53U67A.Q	revised memory map
Keyboard CAN S/W	PHOTOA09	

New Feature

1. SMPTE

- 1.1 Support for internal SMPTE on SP-19.

Known Bugs

- 1. Controllers that are submastering the upper and lower controller banks do not affect spots assigned to controllers.
- 2. Dimmers with a park curve are forced to the Test value in the Test menu.
- 3. Freeing a Loop from A/B and then pressing **[SEQ]** to assign the next memory executes a Loop to the next memory on receiving the Go command.